







VIEW D
SCALE: FULL




SECTION E-E
SHOWN WITH CLAMP FRAME INSTALLED
SCALE: FULL



VIEW C
SCALE: FULL




5.94 FT REF
ITEM 68
HINGE SIDE
ONLY




HOLE FOR ATTACHMENT OF
DOOR CHECK PIVOT
BRACKET TO SIDE
WALL OF COACH
(4) PLACES

HOLE FOR ATTACHMENT OF MOUNTING
FRAME TO SIDE WALL OF COACH
(5) HOLES, (2) THIS SIDE,
(3) OPPOSITE SIDE
BOTTOM HOLE IN EACH HINGE
FOR ATTACHMENT OF
MOUNTING FRAME TO SIDE
WALL OF COACH
(3) PLACES



SECTION B-B
SCALE: FULL

NOTE : SCREWS USED TO SECURE CLAMP FRAME
TO MOUNTING FRAME SUPPLIED BY COACH MANUFACTURER



SCALE: 1/8

SEE SHEET #1 FOR REVISIONS

—	—	—	AS DRAWN	MS	10/10/02
ZONE	E.C. NO.	LETTER	DESCRIPTION OR CHANGE	BY	DATE
— DRAWING BY: —			— CHECKED BY: —	— APPROVED BY: —	—
M.L. SMITH					
OCTOBER 10, 2002					
FINISH: —			NOTED —		
MATERIAL: —			NOTED —		
FILE NAME: —			490277P.SJVC		