

3313470.025 RM1350 Door Flapper Shim Kit Installation Instructions

This Kit includes: (2) Shims

This kit is designed to adjust the fresh food door flapper on RM1350 refrigerators. In some cases the flapper may not be closing fully when the door is closed. See FIG. 1. If this occurs there may not be an adequate seal around the door(s) causing performance issues. When positioned correctly the flapper will be parallel to the door. If the flapper does not operate smoothly or binds up, install one shim below top hinge to adjust flapper as described below. Perform the dollar bill test to check for proper seal. Make sure that the door gasket is fully seated all around the door(s). If flapper still binds or does not operate smoothly, install second shim at same location.

