



A Division of Dura Automotive Systems

1120 North Main Street • Elkhart, IN 46514

PHONE: 574•264•2131 FAX: 574•262•2550


INTERNET: <http://www.atwoodmobile.com>

INFORMATION NOTICE

15K ADJUSTABLE COUPLER WELD INSPECTION OF MPD 81906

3/16/07

In order to improve torsional rigidity and compressive strength, a continuous weld has been placed along the outer perimeter of the Bottom Mount Bracket where it mates to the Adjustable Mounting Bracket. A plug weld has also been added to the forward wing of the Adjustable Mounting Bracket creating a mechanical joint between the Mounting Bracket and the body of the Coupler. Please inspect all 15K Adjustable Couplers, P/N 81906, that you have in your inventory for welds.



LOCATE THE WELDS AS NOTED IN THE ABOVE DRAWING

Couplers that do not exhibit the welds as identified in the verbiage and picture above must be removed and/or isolated.

If you have a 15K Adjustable Coupler that does not have the appropriate welds as described, please contact the Atwood Mobile Products Warranty Department for an RGN # (Return Goods Number) at 800-348-7418, press "0" and ask for the Warranty Department.

The coupler must be returned with the RGN clearly marked on the outside of the package to -

**Atwood Mobile Products
800 Hwy 150 South
West Union, IA 52175**