



CLIMATE CONTROL AIR CONDITIONERS

EN Return Air Grille Replacement Product Change Notice

USA & Canada

Service Office
Dometic Corporation
1120 North Main Street
Elkhart, IN 46514

Service Center & Dealer Locations

Visit:
www.dometic.com

Beginning May 19, 2020, Dometic has introduced non-safety related changes to the Return Air Grille for the Brisk II, Blizzard NXT, and Penguin II air conditioners.

Change Description:

Changes to the Return Air Grille include:

- Mounting hole alignment and bolt clearance changes to improve the installation process when fastening the Return Air Grille to the air conditioner with pass-through fastening bolts.
 - To alleviate the tighter clearance, some of the mounting holes have changed to a mounting slot configuration.
 - To promote better alignment, the mounting slot locations have been re-aligned.
- The newly-designed part has new part numbers for revision tracking purposes.

	Existing Part Number	New Part Number
Return Air Grille Assembly (RAG Assy)	3315930.010	3317404.000
Ceiling Template (Template Ceiling ASM)	not applicable	3316307.002

Action:

Order using the new part numbers identified.