

SOP02575 QAAR 9604 Updating Xantrex Inverter Firmware (No Fault)

Department: 17
People Required: 1

Time to Complete: 2 min
Date Created: Feb 5/2020

Date Revised: Rev #:

Created by Initial: RW Verified: GK

Page 1 of 1


SOP02573

Updating Xantrex Inverter Firmware (With Fault)

Prepare a USB Flash Drive per SOP02573 steps 1 through 8.



Disconnect the unit from shore power



Ensure the inverter is turned on by depressing the button and making sure it is ON on the Dometic Touchscreen.

Technical Data:

Safe Work Procedures:

1



Plug the flash drive into the inverter



The LED will blink green/orange for about 15 seconds



Once the LED has finished flashing.

It will be green for about 5 seconds and then shut

Remove the flash drive at this point.

Notes:

4



Turn off the battery disconnect and unpress the button on the inverter for ONE minute.



Turn on the battery disconnect and the inverter. If the Dometic system shuts it off,

5

8

turn it on through the touch screens.



Verify the update took place by using a mirror to view the inverter display. And press the middle button on the display until you see a "U3 01 05" displayed.

/