

DOMETIC

HEATING

FURNACES

EN Front Grill LD Furnace Service Kit

Product Change Notice

USA & Canada

Service Office
Dometic Corporation
5155 Verdant Drive
Elkhart, IN 46516

Service Center & Dealer Locations

Visit:
dometic.com/support

Effective immediately, the Front Grill LD furnace service kit 30259 is undergoing a non-safety related change.


Change Description:

To improve the installation process for DFS series furnaces, installation kit 30259 is being replaced by installation kit 30260. Kit 30260 includes a trim ring that is not part of the 30259 kit. The trim ring screws into the wall opening and facilitates the attachment of the grill to the furnace.

Action:

Customers who previously ordered installation kit 30259 should now order installation kit 30260 instead.

Existing Part Number	New Part Number
30259	30260



1 Service Kit 30260

① Trim Ring