

DOMETIC

AWNING

SLIDETOPPER

EN SlideTopper bracket hardware

Product Change Notice

USA & Canada

Service Office
Dometic Corporation
5155 Verdant Drive
Elkhart, IN 46516

Service Center & Dealer Locations

Visit:
dometic.com/support

Effective immediately, the Dometic SlideTopper bracket hardware ordering process is undergoing a non-safety related change.

Change description:

To streamline ordering and production, the SlideTopper 15 in. (38 cm) bracket hardware is being phased out.

The following SlideTopper models are affected:
98000, 98001, 98400, 98401, 98410, and 98020.


Action:

Order the SlideTopper 18 in. (46 cm) bracket hardware when replacing either the 15 in. (38 cm) bracket or the 18 in. (46 cm) bracket.

Phased out	Replacement
9800015.40X# ^{1,2}	9800018.40X# ^{1,2}

¹X = 1 (tall) or 2 (short)

²# = U (black) or B (white)



1 SlideTopper bracket hardware